DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720-0036 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: <u>(sb@dhw.idaho.gov</u>

February 18, 2010

RICHARD M. ARMSTRONG - Director

Kathy Prophet, Administrator Preferred Community Homes-- Mallard 7091 West Emerald Street Boise, Idaho 83704

RE: Preferred Community Homes-- Mallard, Provider #13G032

Dear Ms. Prophet:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Preferred Community Homes-- Mallard, on February 9, 2010.

Enclosed is a Statement of Deficiencies/Plan of Correction, Form CMS-2567, listing Medicaid deficiencies and a similar form listing State licensure deficiencies. In the spaces provided on the right side of each sheet, please provide a Plan of Correction. <u>It is important</u> that your Plan of Correction address each deficiency in the following manner:

- 1. What corrective action(s) will be accomplished for those individuals found to have been affected by the deficient practice;
- 2. How you will identify other individuals having the potential to be affected by the same deficient practice and what corrective action(s) will be taken;
- 3. What measures will be put in place or what systemic change you will make to ensure that the deficient practice does not recur;
- 4. How the corrective action(s) will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place; and,
- 5. Include dates when corrective action will be completed. 42 CFR 488.28 states ordinarily a provider is expected to take the steps needed to achieve compliance

Kathy Prophet, Administrator February 18, 2010 Page 2 of 2

within 60 days of being notified of the deficiencies. Please keep this in mind when preparing your plan of correction. For corrective actions which require construction, competitive bidding, or other issues beyond the control of the facility, additional time may be granted.

Sign and date the form(s) in the space provided at the bottom of the first page.

After you have completed your Plan of Correction, return the original to this office by **March 3, 2010**, and keep a copy for your records.

Thank you for the courtesies extended to us during our visit. If you have any questions, please call or write this office at (208) 334-6626.

Sincerely,

TOM MKOZ

Health Facility Surveyor

Fire Life Safety & Construction Program

TM/lj

Enclosure

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

(X1) PROVIDER/SUPPLIER/CLIA

STATEMENT OF DEFICIENCIES

AND PLAN OF CORRECTION

Printed: 02/11/2010 FORM APPROVED OMB NO. 0938-0391

(X3) DATE SURVEY

COMPLETED

IDENTIFICATION NUMBER: A, BUILDING 02 B. WING 13G032 02/09/2010 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 699 S. OTTER PREFERRED COMMUNITY HOMES - MALLAR MERIDIAN, ID 83642 (X5) COMPLETION PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES PRÉFIX (EACH DEFICIENCY MUST BE PRECEEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) K 000! INITIAL COMMENTS K 000 The facility is a single story, Type V(000), residential building. The building is protected throughout except in the garage and attic by a RECEIVED NFPA 13 D fire sprinkler system with quick response sprinkler heads. There is a complete fire alarm/smoke detection system. The facility was built in January of 1996. Currently it is FEB 24 2010 licensed for 8 ICF/MR beds. The following deficiencies were cited at the above FACILITY STANDARDS facility during the annual Fire/Life Safety survey conducted on February 9, 2010. The facility was surveyed under the LIFE SAFETY CODE, 2000 Edition, Chapter 33, Existing Residential Board & Care Occupancies, Impractical Evacuation Capability in accordance with 42 CFR 483.470 (j). The Survey was conducted by: Tom Mroz CFI-II Health Facility Surveyor Fire/Life Safety and Construction K0119 483.470(j)(1)(i) LIFE SAFETY CODE K0119 KO119 483.470(j)(1)(i) LIFE STANDARD SAFETY CODE STANDARD Other hazardous areas are protected in The facility will ensure that a 3" x 3" accordance with 33.2.3.2.3 by one of the open penetration to the 1/2-hour rated following: construction on the ceiling of the gasfired hot heater room will be repaired. (1) An enclosure having a fire resistance rating of not less than 1/2 hour, with a self-closing or Person Responsible: Maintenance, RSC automatic-closing door in accordance with 7.2.1.8 Completion date: 2-26-10 that is equivalent to not less than a 1% inch (4.4) Monitoring: Monthly cm) thick, solid-bonded wood core construction. (2) Automatic sprinkler protection in accordance LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE

(X2) MULTIPLE CONSTRUCTION

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

2-221

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 02/11/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED				
13G032			B. WING		02/09/2010						
NAME OF PROVIDER OR SUPPLIER PREFERRED COMMUNITY HOMES - MALLAR MERIDIAN, ID 83642											
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTIO CROSS-REFERENCED TO THI DEFICIENCY)	TION SHOULD BE COMPLETION DATE					
K0119	Continued From pa with 33.2.3.5, regar	_		K0119							
	Based on observat 1/2-hour rated cons gas-fired hot water practice would affe of one smoke com	ot met as evidenced ion, the facility failed struction on the ceilin heater room. The dect 6 residents and stapartments. The facilitied beds with a censey.	to provide g of the ficient aff, in one y has the	and the second s							
	P.M. on February 9 the 1/2 hour rated of water heater room. The finding was ac	veen 11:00 A.M. and b, 2010, observation receiling in the gas-fired had a 3" x 3" open per knowledged by an e exit interview on Fe	revealed d hot enetration.								
	2010. Actual NFPA stand NFPA 101 §33.2.3.2.3 Other hazardous at of the following: (1) An enclosure hof not less than 1/2 automatic-closing of that is equivalent to -cm) thick, solid-bo	ard: reas shall be protected aving a fire resistance hour, with a self-clost door in accordance we not less than a 13/4 anded wood core consister protection in accordance in accordance would be accordance which a consister protection in accordance with a consister protection with a consister	ed by one ce rating sing or vith 7.2.1.8 -in. (4.4 struction								

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 02/11/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		A. BUILDING	E CONSTRUCTION 02	(X3) DATE S COMPL	(X3) DATE SURVEY COMPLETED					
13G0				B. WING		02/0	02/09/2010					
NAME OF PROVIDER OR SUPPLIER PREFERRED COMMUNITY HOMES - MALLAR 699 S. OTTER												
MERIDIAN, ID 83642												
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN ((EACH CORRECTIVE A CROSS-REFERENCED TO DEFICIE	(X5) COMPLETION DATE						
K0119	Continued From page 2			K0119								
							1					
			; ; 				i 					
l				·								
			:									
			!									
ļ												
				1								
				1			1					
!			!	:			 					
			<u> </u> 									

If continuation sheet 1 of 1

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED 02 A. BUILDING B. WING 02/09/2010 13G032 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 699 S. OTTER PREFERRED COMMUNITY HOMES - MALLARD LAI MERIDIAN, ID 83642 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID ΙĐ (X5) (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE COMPLETE PRÉFIX PREFIX CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DATE DEFICIENCY) M 000 16.03.11 Inital Comments M 000 The facility is a single story, Type V(000), residential building. The building is protected throughout except in the garage and attic by a NFPA 13 D fire sprinkler system with guick response sprinkler heads. There is a complete fire alarm/smoke detection system. The facility was built in January of 1996. Currently it is licensed for 8 ICF/MR beds. RECEIVED The following deficiencies were cited at the above facility during the annual Fire/Life Safety survey conducted on February 8, 2010. The FEB 24 2010 facility was surveyed in accordance with IDAPA 16.03.11. FACILITY STANDARDS The Survey was conducted by: Tom Mroz CFI-II Health Facility Surveyor Fire/Life Safety and Construction MM309 16.03.11.110 Fire and Life Safety Standards MM309 MM309 16.03.11.110 FIRE AND Buildings on the premises used as facilities must LIFE SAFETY STANDARDS meet all the requirements of local, state and national codes concerning fire and life safety Refer to K0119 standards that are applicable to ICF/MR facilities. This Rule is not met as evidenced by: Refer to federal deficiency K 119, fire resistance rating, listed on the CMS 2567 form. LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE

ENXD21

Bureau of Facility Standards